




Dimensions



- *Distance from bottom of sink to centre line of disposer outlet. Add 12.7 mm when stainless steel sinks are used.
- **Length of tailpipe from centre line of disposer outlet to end of tailpipe.
- ***Distance between bottom of sink bowl to the waste pipe to be minimum of 30 cm.

ADVANCED SERIES

Evolution Plus 1000 SR

Benefits

This model offers the following benefits:

- Food waste is ground into particles and flushed away
- A convenient solution to food waste in the home
- Lift & Latch Technology and rubber grips on trim shell make it easy to install into new or existing kitchens and can be fitted to most sinks
- By using your disposal regularly, you can help divert food waste from landfills and reduce greenhouse gas emissions.

Features

This model offers the following features:

- 1 HP induction motor provides maximum grinding power and durability
- Quietest SoundSeal Technology is our quietest disposal on the market
- Advanced Grind for tough and fibrous food scraps
- 4-Stage MultiGrind Technology.
 Finest grind (Compared to 1, 2 or 3-Stage MultiGrind Technology)
- · Removable Antimicrobial Baffle
- Air Switch in 3 finishes (Matte black, Brushed Steel and Chrome)

Warranty

8-Year In-home Warranty

Specifications

Type of Feed	Continuous
On/Off Control	Air Switch
Motor	Single Phase
Motor HP	1
Volts	220-240
HZ	50-60
Motor Power, W	450W
Time Rating	Intermittent
Lubrication	Permanently Lubricated Upper & Lower Bearings
Shipping Weight (Approx.)	9.16 kg
Overall Height	31.2 cm
Motor Protection	Automatic Reset
Drain Connection	3.8 cm Anti-Vibration (Hose Clamp)
Dishwasher Drain Connection	No
Grind Technology	4-Stage MultiGrind Technology
Plug	10 amp plug
Grind Chamber Capacity	980 ml



insinkerator.co.nz

For more information contact Parex Industries Limited on Tel: 0800 200 510 or email: info.parex@emerson.com

InSinkErator reserves the right to change product specifications without prior notice. The disposer described in this leaflet is for household use: usage in commercial situations is not covered by warranty.