




#### **Dimensions**



- \*Distance from bottom of sink to centre line of disposer outlet. Add 12.7 mm when stainless steel sinks are used.
- \*\*Length of tailpipe from centre line of disposer outlet to end of tailpipe.
- \*\*\*Distance between bottom of sink bowl to the waste pipe to be minimum of 30 cm.

## **ADVANCED SERIES**

# **Evolution Plus 750 SR**

#### **Benefits**

This model offers the following benefits:

- Food waste is ground into particles and flushed away
- A convenient solution to food waste in the home
- Lift & Latch Technology and grips on trim shell make it easy to install into new or existing kitchens and can be fitted to most sinks.
- By using your disposal regularly, you can help divert food waste from landfills and reduce greenhouse gas emissions.

#### **Features**

This model offers the following features:

- 0.75 HP induction motor provides maximum grinding power and durability
- · Quiet SoundSeal Technology
- Advanced Grind for tough and fibrous food scraps
- 3-Stage MultiGrind Technology.
  Finest grind (Compared to 1- and 2-Stage MultiGrind Technology)
- · Removable Antimicrobial Baffle
- Air Switch in 3 finishes (Matte Black, Brushed Steel & Chrome).

## **Specifications**

Type of Feed	Continuous
On/Off Control	Air Switch
Motor	Single Phase
Motor HP	0.75
Volts	220-240
HZ	50-60
Motor Power, W	380 W
Time Rating	Intermittent
Lubrication	Permanently Lubricated Upper & Lower Bearings
Shipping Weight (Approx.)	8.34 kg
Overall Height	31.2 cm
Motor Protection	Automatic Reset
Drain Connection	3.8 cm Cushioned Slip Joint
Dishwasher Drain Connection	No
Grind Technology	3-Stage MultiGrind Technology
Plug	10 amp plug
Grind Chamber Capacity	980 ml

## Warranty

5-Year In-home Warranty



#### insinkerator.co.nz

For more information contact Parex Industries Limited on Tel: 0800 200 510 or email: info.parex@emerson.com

InSinkErator reserves the right to change product specifications without prior notice. The disposer described in this leaflet is for household use: usage in commercial situations is not covered by warranty.